




- Widen Path, remove sloughing & Drainage Problems, reduce grade to 5%
- Crossing at Cliveden should be upgraded. Sign pointing in the wrong direction. Adjust sign to have arrow pointing straight towards crosswalk on north side.
- 3. Upgrade signing and access through Cliveden intersection
- 4. Fix sloughing, widen path
- New guide sign at N20. Widen sidewalk locally on West side only
- 6. New guide sign at N15. Widen sidewalk locally, both sides.
- 7. Sign pointing in the wrong direction. Change tab to have arrow pointing left and not right as shown here. (Currently points towards a parking lot)
- 8. Install sign as shown to direct cyclist traffic to bridge.
- 9. Install sign as shown to direct cyclist traffic towards New Westminister and Richmond.
- 10. Install Zw-054R on beginning of fencing. Flare Hand Rail
- Install Zw-054L on beginning of fencing. Fix trail. Flare Hand Rail



- 12. Existing guide sign at Nxxx. Widen sidewalk locally
- 13. Install Zw-054L on first bridge pillar in SB direction.
- 14. Install Zw-054R on first bridge pillar in SB direction.



- 15. Existing guide sign at Nxxx. Widen sidewalk locally
- 16. Install Zw-054R on first bridge pillar in NB direction.
- 17. Install Zw-054L on first bridge pillar in NB direction.





18. Improve Access, Widen Path, Repave, lower grade.

Retaining wall, relocate lamp standard, shrub trimming, flare/widen switchback

- 19. Improve Access, Widen Path, Repave, lower grade (replace bricks with paved path). Retaining wall, flare/widen switchback
- 20. Keep existing sign and cut shrubbery so that sign is not obstructed.
- 21. Keep existing sign (Nordel way east/river road) and install new guide sign (highway 17, ferries, etc.).
- 22. Keep existing sign (Nordel way east/river road) and install new guide sign (highway 17, ferries, etc.).
- 23. Keep existing sign (Alex Fraser Bridge/River Road) and install new guide sign (highway 17, ferries, etc.).